
Table of Contents

Preface.....	v
Author's Preface	vii
Acknowledgments.....	xi

Chapter 1

An Introduction to Dynamic Mechanical Analysis	1
1.1 A Brief History of DMA.....	1
1.2 Basic Principles	2
1.3 Sample Applications.....	5
1.4 Creep-Recovery Testing.....	11
1.5 Odds and Ends.....	13
Notes	15

Chapter 2

Basic Rheological Concepts: Stress, Strain, and Flow	17
2.1 Force, Stress, and Deformation.....	17
2.2 Applying the Stress	18
2.3 Hooke's Law: Defining the Elastic Response.....	21
2.4 Liquid-Like Flow or the Viscous Limit	24
2.5 Another Look at the Stress-Strain Curves.....	27
Appendix 2.1 Conversion Factors	35
Notes	37

Chapter 3

Rheology Basics: Creep-Recovery and Stress Relaxation.....	39
3.1 Creep-Recovery Testing.....	39
3.2 Models to Describe Creep-Recovery Behavior.....	42
3.3 Analyzing a Creep-Recovery Curve to Fit the Four-Element Model.....	45
3.4 Analyzing a Creep Experiment for Practical Use	47
3.5 Other Variations on Creep Tests.....	48
3.6 A Quick Look at Stress Relaxation Experiments.....	51
3.7 Superposition — The Boltzmann Principle	51
3.8 Retardation and Relaxation Times	52
3.9 Structure-Property Relationships in Creep-Recovery Tests	53
3.10 Thermomechanical Analysis	54
Notes	58

Chapter 4

Dynamic Testing	61
4.1 Applying a Dynamic Stress to a Sample	61
4.2 Calculating Various Dynamic Properties	64
4.3 Instrumentation for DMA Tests	66
4.3.1 Forced Resonance Analyzers	66
4.3.2 Stress and Strain Control	67
4.3.3 Axial and Torsional Deformation.....	68
4.3.4 Free Resonance Analyzers	69
4.4 Fixtures or Testing Geometries	72
4.4.1 Axial	72
4.4.2 Torsional	78
4.5 Calibration Issues	80
4.6 Dynamic Experiments	84
Appendix 4.1 Calibration and Verification of an Instrument	85
Notes	89

Chapter 5

Time-Temperature Scans: Transitions in Polymers.....	91
5.1 Time and Temperature Scanning in the DMA.....	91
5.2 Transitions in Polymers: Overview.....	91
5.3 Sub- T_g Transitions	95
5.4 The Glass Transition (T_g or T_α).....	100
5.5 The Rubbery Plateau, T_α^* and T_β	102
5.6 The Terminal Region.....	109
5.7 Frequency Dependencies in Transition Studies	112
5.8 Practice Problems and Applications.....	115
5.9 Time-Based Studies	118
5.10 Conclusions.....	121
Notes	121

Chapter 6

Time and Temperature Studies: Thermosets.....	125
6.1 Thermosetting Materials: A Review.....	125
6.2 Study of Curing Behavior in the DMA: Cure Profiles.....	128
6.3 Photo-Curing.....	136
6.4 Modeling Cure Cycles.....	138
6.5 Isothermal Curing Studies	138
6.6 Kinetics by DMA	138
6.7 Mapping Thermoset Behavior: The Gilham-Enns Diagram.....	142
6.8 QC Approaches to Thermoset Characterization	143
6.9 Post-Cure Studies	147
6.10 Conclusions.....	147
Notes	147

Chapter 7

Frequency Scans	149
7.1 Methods of Performing a Frequency Scan	149
7.2 Frequency Effects on Materials	151
7.3 The Deborah Number	160
7.4 Frequency Effects on Solid Polymers	162
7.5 Frequency Effects during Curing Studies	163
7.6 Frequency Studies on Polymer Melts	165
7.7 Normal Forces and Elasticity	166
7.8 Master Curves and Time–Temperature Superposition	168
7.9 Transformations of Data	173
7.10 Molecular Weight and Molecular Weight Distributions	174
7.11 Conclusions	178
Notes	180

Chapter 8

DMA Applications to Real Problems: Guidelines	183
8.1 The Problem: Material Characterization or Performance	183
8.2 Performance Tests: To Model or to Copy	183
8.3 Choosing a Type of Test	187
8.4 Characterization	188
8.5 Choosing the Fixture	188
8.6 Checking the Response to Loads	189
8.7 Checking the Response to Frequency	189
8.8 Checking the Response to Time	190
8.9 Checking the Temperature Response	191
8.10 Putting It Together	191
8.11 Verifying the Results	192
8.12 Supporting Data from Other Methods	193
Appendix 8.1 Sample Experiments for the DMA	193
Notes	195
Index	199