
Contents

FUNDAMENTALS

Chapter 1 Properties of X-rays

1-1	Introduction	3
1-2	Electromagnetic radiation	3
1-3	The continuous spectrum	6
1-4	The characteristic spectrum	8
1-5	Absorption	13
1-6	Filters	19
1-7	Production of x-rays	21
1-8	Detection of x-rays	27
1-9	Safety precautions	29

Chapter 2 Geometry of Crystals

2-1	Introduction	32
2-2	Lattices	32
2-3	Crystal systems	34
2-4	Symmetry	37
2-5	Primitive and nonprimitive cells	39
2-6	Lattice directions and planes	41
2-7	Crystal structure	47
2-8	Atom sizes and coordination	56
2-9	Crystal shape	58
2-10	Twinned crystals	59
2-11	The stereographic projection	63

Chapter 3 Diffraction I: Directions of Diffracted Beams

3-1	Introduction	81
3-2	Diffraction	82
3-3	The Bragg law	86
3-4	X-ray spectroscopy	88
3-5	Diffraction directions	91
3-6	Diffraction methods	92
3-7	Diffraction under nonideal conditions	99

Chapter 4 Diffraction II: Intensities of Diffracted Beams

4-1	Introduction	107
4-2	Scattering by an electron	107
4-3	Scattering by an atom	111
4-4	Scattering by a unit cell	115
4-5	Some useful relations	121
4-6	Structure-factor calculations	121
4-7	Application to powder method	126
4-8	Multiplicity factor	127
4-9	Lorentz factor	127
4-10	Absorption factor	132
4-11	Temperature factor	135
4-12	Intensities of powder pattern lines	139
4-13	Examples of intensity calculations	140
4-14	Measurement of x-ray intensity	143

EXPERIMENTAL METHODS**Chapter 5 Laue Photographs**

5-1	Introduction	149
5-2	Cameras	150
5-3	Specimens and holders	155
5-4	Collimators	156
5-5	The shapes of Laue spots	158

Chapter 6 Powder Photographs

6-1	Introduction	161
6-2	Debye-Scherrer method	162
6-3	Specimen preparation	166
6-4	Film loading	167
6-5	Cameras for special conditions	168
6-6	Focusing cameras	170
6-7	Seemann-Bohlin camera	170
6-8	Back-reflection focusing cameras	172
6-9	Pinhole photographs	175
6-10	Microbeams and microcameras	177
6-11	Choice of radiation	178
6-12	Background radiation	179
6-13	Crystal monochromators	180
6-14	Guinier cameras	183
6-15	Measurement of line position	184
6-16	Measurement of line intensity	185

Chapter 7 Diffractometer and Spectrometer Measurements

7-1	Introduction	188
7-2	General features	189

7-3	X-ray optics	196
7-4	Counters (general)	199
7-5	Proportional counters	204
7-6	Geiger counters	208
7-7	Scintillation counters	208
7-8	Semiconductor counters	210
7-9	Pulse-height analysis	213
7-10	Special kinds of diffractometry	217
7-11	Scalers	219
7-12	Ratemeters	222
7-13	Monochromatic operation	226

APPLICATIONS

Chapter 8 Orientation and Quality of Single Crystals

8-1	Introduction	233
	<i>Crystal Orientation</i>	
8-2	The back-reflection Laue method	233
8-3	Transmission Laue method	247
8-4	Diffractometer method	250
8-5	Setting a crystal in a required orientation	256
	<i>Crystal Quality</i>	
8-6	Laue methods	260
8-7	Topographic and other methods	268

Chapter 9 Structure of Polycrystalline Aggregates

9-1	Introduction	281
	<i>Crystal Size</i>	
9-2	Grain size	281
9-3	Particle size	284
	<i>Crystal Quality</i>	
9-4	Crystal quality	285
9-5	Depth of x-ray penetration	292
	<i>Crystal Orientation</i>	
9-6	General	295
9-7	The texture of wire (photographic method)	300
9-8	The texture of sheet (diffractometer methods)	303
9-9	The texture of wire (diffractometer method)	316
9-10	Inverse pole figures	319
	<i>Amorphous Solids</i>	
9-11	Amorphous and semi-amorphous solids	321
9-12	Summary	321

Chapter 10 Determination of Crystal Structure

10-1	Introduction	324
10-2	Preliminary treatment of data	326
10-3	Indexing patterns of cubic crystals	327
10-4	Indexing patterns of noncubic crystals (graphical methods)	330
10-5	Indexing patterns of noncubic crystals (analytical methods)	337
10-6	The effect of cell distortion on the powder pattern	340
10-7	Determination of the number of atoms in a unit cell	342
10-8	Determination of atom positions	343
10-9	Example of structure determination	345

Chapter 11 Precise Parameter Measurements

11-1	Introduction	350
11-2	Debye-Scherrer cameras	352
11-3	Back-reflection focusing cameras	358
11-4	Pinhole cameras	358
11-5	Diffractometers	359
11-6	Method of least squares	360
11-7	Cohen's method	363
11-8	General	367

Chapter 12 Phase-Diagram Determination

12-1	Introduction	369
12-2	General principles	370
12-3	Solid solutions	375
12-4	Determination of solvus curves (disappearing-phase method)	377
12-5	Determination of solvus curves (parametric method)	379

Chapter 13 Order-Disorder Transformations

13-1	Introduction	383
13-2	Long-range order in AuCu_3	383
13-3	Other examples of long-range order	389
13-4	Detection of superlattice lines	391
13-5	Short-range order and clustering	394

Chapter 14 Chemical Analysis by X-ray Diffraction

14-1	Introduction	397
	<i>Qualitative Analysis</i>	
14-2	Basic principles	398
14-3	Powder diffraction file	398
14-4	Procedure	401
14-5	Examples of analysis	402
14-6	Practical difficulties	406

Quantitative Analysis (Single Phase)

14-7	Chemical analysis by parameter measurement	407
------	--	-----

Quantitative Analysis (Multiphase)

14-8	Basic principles	407
14-9	External standard method	409
14-10	Direct comparison method	411
14-11	Internal standard method	415
14-12	Practical difficulties	417

Chapter 15 Chemical Analysis by X-ray Spectrometry

15-1	Introduction	421
15-2	General principles	423
	<i>Wavelength Dispersion</i>	
15-3	Spectrometers	425
15-4	Intensity and resolution	432
15-5	Qualitative analysis	434
15-6	Quantitative analysis	434
	<i>Energy Dispersion</i>	
15-7	Spectrometers	439
15-8	Intensity and resolution	439
15-9	Excitation and filtration	441
15-10	Chemical analysis	442
	<i>Microanalysis</i>	
15-11	Microanalysis	444

Chapter 16 Measurement of Residual Stress

16-1	Introduction	447
16-2	Applied stress and residual stress	448
16-3	General principles	451
16-4	Diffractometer method	456
16-5	Photographic method	469
16-6	Calibration	472
16-7	Precision and accuracy	474
16-8	Practical difficulties	476

Appendices

1	The Reciprocal Lattice	480
2	Electron and Neutron Diffraction	497
3	Lattice Geometry	501
4	The Rhombohedral-Hexagonal Transformation	504
5	Crystal Structures of Some Elements	506
6	Crystal Structures of Some Compounds and Solid Solutions	508
7	X-Ray Wavelengths	509

8	Mass Absorption Coefficients and Densities	512
9	Values of $\sin^2 \theta$	514
10	Quadratic Forms of Miller Indices	516
11	Values of $(\sin \theta) / \lambda (\text{\AA}^{-1})$	518
12	Atomic Scattering Factors	520
13	Multiplicity Factors for the Powder Method	523
14	Lorentz-Polarization Factor	524
15	Data for Calculation of the Temperature Factor	526
16	Atomic Weights	527
17	Physical Constants	528
	General References.	529
	Chapter References.	534
	Answers to Selected Problems	543
	Index	547