

Contents

| | |
|---|-----------|
| Preface to the Second Edition | xv |
| Chapter 1 Catalyzing the Generation of Knowledge | 1 |
| 1.1. The Learning Process | 1 |
| 1.2. Important Considerations | 5 |
| 1.3. The Experimenter's Problem and Statistical Methods | 6 |
| 1.4. A Typical Investigation | 9 |
| 1.5. How to Use Statistical Techniques | 13 |
| References and Further Reading | 14 |
| Chapter 2 Basics (Probability, Parameters, and Statistics) | 17 |
| 2.1. Experimental Error | 17 |
| 2.2. Distributions | 18 |
| 2.3. Statistics and Parameters | 23 |
| 2.4. Measures of Location and Spread | 24 |
| 2.5. The Normal Distribution | 27 |
| 2.6. Normal Probability Plots | 33 |
| 2.7. Randomness and Random Variables | 34 |
| 2.8. Covariance and Correlation as Measures of Linear Dependence | 37 |
| 2.9. Student's <i>t</i> Distribution | 39 |
| 2.10. Estimates of Parameters | 43 |
| 2.11. Random Sampling from a Normal Population | 44 |
| 2.12. The Chi-Square and <i>F</i> Distributions | 46 |
| 2.13. The Binomial Distribution | 48 |
| 2.14. The Poisson Distribution | 54 |

| | |
|---|-----|
| Appendix 2A. Mean and Variance of Linear Combinations of Observations | 57 |
| References and Further Reading | 60 |
| Chapter 3 Comparing Two Entities: Reference Distributions, Tests, and Confidence Intervals | 67 |
| 3.1. Relevant Reference Sets and Distributions | 67 |
| 3.2. Randomized Paired Comparison Design: Boys' Shoes Example | 81 |
| 3.3. Blocking and Randomization | 92 |
| 3.4. Reprise: Comparison, Replication, Randomization, and Blocking in Simple Experiments | 94 |
| 3.5. More on Significance Tests | 94 |
| 3.6. Inferences About Data that are Discrete: Binomial Distribution | 105 |
| 3.7. Inferences about Frequencies (Counts Per Unit): The Poisson Distribution | 110 |
| 3.8. Contingency Tables and Tests of Association | 112 |
| Appendix 3A. Comparison of the Robustness of Tests to Compare Two Entities | 117 |
| Appendix 3B. Calculation of reference distribution from past data | 120 |
| References and Further Reading | 123 |
| Chapter 4 Comparing a Number of Entities, Randomized Blocks, and Latin Squares | 133 |
| 4.1. Comparing k Treatments in a Fully Randomized Design | 133 |
| 4.2. Randomized Block Designs | 145 |
| 4.3. A Preliminary Note on Split-Plot Experiments and their Relationship to Randomized Blocks | 156 |
| 4.4. More than one blocking component: Latin Squares | 157 |
| 4.5. Balanced Incomplete Block Designs | 162 |
| Appendix 4A. The Rationale for the Graphical ANOVA | 166 |
| Appendix 4B. Some Useful Latin Square, Graeco–Latin Square, and Hyper-Graeco–Latin Square Designs | 167 |
| References and Further Reading | 168 |
| Chapter 5 Factorial Designs at Two Levels | 173 |
| 5.1. Introduction | 173 |

| | |
|---|-----|
| 5.2. Example 1: The Effects of Three Factors (Variables) on Clarity of Film | 174 |
| 5.3. Example 2: The Effects of Three Factors on Three Physical Properties of a Polymer Solution | 175 |
| 5.4. A 2^3 Factorial Design: Pilot Plant Investigation | 177 |
| 5.5. Calculation of Main Effects | 178 |
| 5.6. Interaction Effects | 181 |
| 5.7. Genuine Replicate Runs | 183 |
| 5.8. Interpretation of Results | 185 |
| 5.9. The Table of Contrasts | 186 |
| 5.10. Misuse of the ANOVA for 2^k Factorial Experiments | 188 |
| 5.11. Eyeing the Data | 190 |
| 5.12. Dealing with More Than One Response: A Pet Food Experiment | 193 |
| 5.13. A 2^4 Factorial Design: Process Development Study | 199 |
| 5.14. Analysis Using Normal and Lenth Plots | 203 |
| 5.15. Other Models for Factorial Data | 208 |
| 5.16. Blocking the 2^k Factorial Designs | 211 |
| 5.17. Learning by Doing | 215 |
| 5.18. Summary | 219 |
| Appendix 5A. Blocking Larger Factorial Designs | 219 |
| Appendix 5B. Partial Confounding | 221 |
| References and Further Reading | 222 |
| Chapter 6 Fractional Factorial Designs | 235 |
| 6.1. Effects of Five Factors on Six Properties of Films in Eight Runs | 235 |
| 6.2. Stability of New Product, Four Factors in Eight Runs, a 2^{4-1} Design | 236 |
| 6.3. A Half-Fraction Example: The Modification of a Bearing | 239 |
| 6.4. The Anatomy of the Half Fraction | 240 |
| 6.5. The 2^{7-4}_{III} Design: A Bicycle Example | 244 |
| 6.6. Eight-Run Designs | 246 |
| 6.7. Using Table 6.6: An Illustration | 247 |
| 6.8. Sign Switching, Foldover, and Sequential Assembly | 249 |
| 6.9. An Investigation Using Multiple-Column Foldover | 252 |
| 6.10. Increasing Design Resolution from III to IV by Foldover | 257 |
| 6.11. Sixteen-Run Designs | 258 |

| | |
|---|-----|
| 6.12. The 2^{5-1} Nodal Half Replicate of the 2^5 Factorial: Reactor Example | 259 |
| 6.13. The 2^{8-4}_{IV} Nodal Sixteenth Fraction of a 2^8 Factorial | 263 |
| 6.14. The 2^{15-11}_{III} Nodal Design: The Sixty-Fourth Fraction of the 2^{15} Factorial | 266 |
| 6.15. Constructing Other Two-Level Fractions | 269 |
| 6.16. Elimination of Block Effects | 271 |
| References and Further Reading | 273 |
| Chapter 7 Additional Fractionals and Analysis | 281 |
| 7.1. Plackett and Burman Designs | 281 |
| 7.2. Choosing Follow-Up Runs | 294 |
| 7.3. Justifications for the Use of Fractionals | 303 |
| Appendix 7A. Technical Details | 305 |
| Appendix 7B. An Approximate Partial Analysis for PB Designs | 308 |
| Appendix 7C. Hall's Orthogonal Designs | 310 |
| References and Further Reading | 313 |
| Chapter 8 Factorial Designs and Data Transformation | 317 |
| 8.1. A Two-Way (Factorial) Design | 317 |
| 8.2. Simplification and Increased Sensitivity from Transformation | 320 |
| Appendix 8A. Rationale for Data Transformation | 329 |
| Appendix 8B. Bartlett's χ^2 for Testing Inhomogeneity of Variance | 329 |
| References and Further Reading | 329 |
| Chapter 9 Multiple Sources of Variation | 335 |
| 9.1. Split-Plot Designs, Variance Components, and Error Transmission | 335 |
| 9.2. Split-Plot Designs | 335 |
| 9.3. Estimating Variance Components | 345 |
| 9.4. Transmission of Error | 353 |
| References and Further Reading | 359 |
| Chapter 10 Least Squares and Why We Need Designed Experiments | 363 |
| 10.1. Estimation With Least Squares | 364 |
| 10.2. The Versatility of Least Squares | 378 |
| 10.3. The Origins of Experimental Design | 397 |

| | |
|---|------------|
| 10.4. Nonlinear Models | 407 |
| Appendix 10A. Vector Representation of Statistical Concepts | 410 |
| Appendix 10B. Matrix Version of Least Squares | 416 |
| Appendix 10C. Analysis of Factorials, Botched and Otherwise | 418 |
| Appendix 10D. Unweighted and Weighted Least Squares | 420 |
| References and Further Reading | 424 |
| Chapter 11 Modeling, Geometry, and Experimental Design | 437 |
| 11.1. Some Empirical Models | 441 |
| 11.2. Some Experimental Designs and the Design Information Function | 447 |
| 11.3. Is the Surface Sufficiently Well Estimated? | 453 |
| 11.4. Sequential Design Strategy | 454 |
| 11.5. Canonical Analysis | 461 |
| 11.6. Box–Behnken Designs | 475 |
| References and Further Reading | 483 |
| Chapter 12 Some Applications of Response Surface Methods | 489 |
| 12.1. Iterative Experimentation To Improve a Product Design | 489 |
| 12.2. Simplification of a Response Function by Data Transformation | 503 |
| 12.3. Detecting and Exploiting Active and Inactive Factor Spaces for Multiple-Response Data | 509 |
| 12.4. Exploring Canonical Factor Spaces | 513 |
| 12.5. From Empiricism to Mechanism | 518 |
| 12.6. Uses of RSM | 526 |
| Appendix 12A. Average Variance of \hat{y} | 526 |
| Appendix 12B. | 528 |
| References and Further Reading | 530 |
| Chapter 13 Designing Robust Products and Processes: An Introduction | 539 |
| 13.1. Environmental Robustness | 539 |
| 13.2. Robustness To Component Variation | 549 |
| Appendix 13A. A Mathematical Formulation for Environmental Robustness | 556 |
| Appendix 13B. Choice of Criteria | 558 |
| References and Further Reading | 559 |

| | |
|--|------------|
| Chapter 14 Process Control, Forecasting, and Time Series: An Introduction | 565 |
| 14.1. Process Monitoring | 565 |
| 14.2. The Exponentially Weighted Moving Average | 569 |
| 14.3. The CuSum Chart | 574 |
| 14.4. Process Adjustment | 576 |
| 14.5. A Brief Look At Some Time Series Models and Applications | 585 |
| 14.6. Using a Model to Make a Forecast | 588 |
| 14.7. Intervention Analysis: A Los Angeles Air Pollution Example | 593 |
| References and Further Reading | 595 |
| Chapter 15 Evolutionary Process Operation | 599 |
| 15.1. More than One Factor | 602 |
| 15.2. Multiple Responses | 606 |
| 15.3. The Evolutionary Process Operation Committee | 607 |
| References and Further Reading | 608 |
| Appendix Tables | 611 |
| Author Index | 625 |
| Subject Index | 629 |